













28 450 809 Produktversion von 13.03.2017 bis 06.07.2018



- Brauseabgang 3/8"
- Rosette Ø 60 mm
- Anschluss 1/2"

Eigensicher gegen Rückfließen.

	Platin	28 450 809-08
	Chrom	28 450 809-00
	Platin gebürstet	28 450 809-06
	Dark Brass matt	28 450 809-16
	Dark Bronze matt	28 450 809-17
	Dark Chrome	28 450 809-19
	Light Gold gebürstet	28 450 809-27
	Messing gebürstet (23kt Gold)	28 450 809-28
	Bronze gebürstet	28 450 809-42
	Champagne gebürstet (22kt Gold)	28 450 809-46
	Champagne (22kt Gold)	28 450 809-47
	Dark Platinum gebürstet	28 450 809-99


Empfohlenes Zubehör

- UP-Wandwinkel -** 35 085 970 90
- Min. Einbautiefe 90 mm
  - Max. Einbautiefe 163 mm




28 450 809 Produktversion von 13.03.2017 bis 06.07.2018

mm [inches]



**Durchflussdiagramm**



**Codes & Standards**

ASME A112.18.1

cUPC

EN 1717

Scottish Water  
Byelaws

UK Water Supply  
Regulations



## VAIA Wandanschlussbogen - Platin

VAIA


---

28 450 809 Produktversion von 13.03.2017 bis 06.07.2018

### Zertifikate

---

Belgaqua\_22\_280\_2 IAPMO\_4976 WRAS\_240702



### Ersatzteilstückliste

Nr.	Artikelnummer	Benennung	Verbaumenge	Lieferzeit
4	09 11 03 123-08	Anschluss 22 x 48 x 87 mm - Platin	1,00	40
1	90 27 80 021 00-08	Rosette Ø 60 x 18 mm - Platin	1,00	40
3	90 23 01 040 00 90	Rückflussverhinderer RV-Patrone DW15 -	2,00	2
5	90 21 02 069 00-08	Haube / Hülse - Platin	1,00	40
2	09 16 01 014 90	Ring Sicherungsring Ø 15 x 1 mm -	1,00	2